



Old electric motor,
with thermal sensor
5 cables



New electric motor,
with thermal sensor
inside
3 cables



* REMOVE THE
TERMINAL PLUG

CHECK THE ROTATION OF THE MOTOR.
ALL THE MOTORS IN THE OVEN MUST
TURN SAME SIDE.

2	Capacitor 6,3 microF		1
1/B	MOT00164 new version	MOT00162	1
1/A	MOT00164 old version	MOT00162	1
POS.	DENOMINAZIONE	CODICE	Q.TA'

DESCRIPTION/DESCRIZIONE
SOSTITUZIONE MOTORE VENTILAZIONE LILLIPUT 15
REPLACEMENT VENTILATION MOTOR LILLIPUT 15



DRAFTED/DISEGNATO	DATE/DATA	SCALE/SCALA	CODE/CODICE	SHEET/FOGLIO	APPROVED/APPROVATO	DATE/DATA
Soave	30/07/2020	- -	IMPI0197	1/1	Farina Simone	30/07/2020

ISSUE/MODIFICA

This drawing is the property of Dr. Zanussi s.r.l. It must not be disclosed
copied or used for production without its written authorization.

Questo disegno è di esclusiva proprietà della ditta Dr. Zanussi s.r.l. che ne vieta la
copia e l'uso per la produzione, senza il proprio consenso scritto